

Audit Details

Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	16/02/2024
Auditor:	David Pinto
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Incendio o explosion / Fire or explosion
Breve descripción del evento / Brief Event Description	16 de febrero 2024, Simulacro en TMF Presa Norte, celda 3 Fuego en excavadora con herido y rescate February 16, 2024, Drill at TMF Presa Norte, cell 3 Fire in excavator with injury and rescue
Especificar ubicación / Specify Location	TMF, Presa Norte, celda 3
Hora de inicio / Starting Time	15:19
Hora de finalización / Ending Time	15:10
Departamento / Department	TMF - Earthworks
Descripción de la emergencia	Durante la tarea de control de erosión el operador realiza actividades de perfilado de talud, al momento de trasladar el equipo para la siguiente banqueta de trabajo siente un olor a quemado y observa humo saliendo de la zona del motor, efectua el proceso de aplicación del sistema AFEX pero sin éxito, el operador al notar la falla del sistema AFEX procede a descender del equipo y refugiarse. Durante el proceso de salida del operador el equipo queda envuelto en llamas. During the erosion control task the operator performs slope profiling activities, at the time of moving the equipment to the next work bench he smells a burning odor and sees smoke coming out of the engine area, he performs the AFEX system application process but without success, the operator noticing the failure of the AFEX system proceeds to descend from the equipment and take refuge. During the operator's exit process, the equipment is engulfed in flames.

Notes

16 de febrero 2024, Simulacro en TMF Presa Norte, celda 3 Fuego en excavadora con herido y rescate

Notas

- 1.Se ha determinado que existen punto de trabajos de difícil acceso, que es necesario el utilizar sistemas de rescate.
- 2.No se presentó personal de seguridad física.
- 3.No hubo participación de los miembros de seguridad industrial del TMF. El supervisor no hizo la coordinación con los oficiales de seguridad del área.

February 16, 2024, Drill at TMF Presa Norte, cell 3 Fire in excavator with injury and rescue

- Notes
- 1.It has been determined that there are difficult access points, which require the use of rescue systems.
 - 2.No physical security personnel were present.
 - 3.There was no participation of TMF industrial safety members. The supervisor did not coordinate with the area security officers.

Response Summary

Section	Completed	Not completed
Audit	1	0

Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

Capacity: supervisor

Name: David Pinto



Documents



camillaje



Rescate